

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 22/AE-III (Comp)/2025

Dated: 10/06/2025

It is certified that the existing building **STUDY HALL SCHOOL** (name of the building or premises) at **PIPERSAND, SAROJINI NAGAR, LUCKNOW** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 02	NA	NA	NA	NA	NA

The building is owned/occupied by **STUDY HALL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Works Department (U.P.)** (Name of Department/ Govt.) on **10-06-2025** (date of inspection) in the presence of **Mrs. ANJANA PANDEY, Principal of STUDY HALL SCHOOL** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **10-06-2025** for a period of **10** years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on **10-06-2025** at **Lucknow** by **Assistant Engineer.**

scan

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : .....

Name : **Vyas Muni**  
सहायक अभियंता  
निर्माण खण्ड-1, लो0नि0वि0.  
Designation : **Assistant Engineer**  
लेखन0

Name & Address of Department/Office : **CD-1, PWD, Lucknow**